Villas at Summit Reserve Condos Maintanance			
A= Association Responsibility			
O= Owner Responsibility			
Air Conditioner Unit	О	Interior Repairs due to Exterior Repairs	A/O
Boots (Roof)	A	Keys	О
Chimney Caps/Screens	A	Lights, Front Door	A
Common Areas	A	Lights, Garage	О
Door Locks	O	Lights, Porch/Patio	A
Door Painting	A	Lights, Street	A
Doors (frames, etc)	О	Mail Boxes	A
Electrical Outlets (Exterior)	A	Mail Box Keys	A
Exterminating	О	Mail Box Key Replacement	О
Events of Mother Nature	О	Mail Box Maintenance/Replacement	Α
Faucets	О	Painting (Exterior)	Α
Furnace	О	Patios	О
Foundation Slab	O	Patio Maintenance or repair	О
Garage Door	О	Patio Fences	A
Garage Door Mechanism	О	Roof	A
Garage Floor	O	Roof & Dryer Vents	О
Gutter/Downspouts Maint/Cleaning	A	Sidewalks	A
Hot Water Tanks	О	Shutters	A
Insurance (Common Areas)	A	windows (sears, caurk, repracement,	О
Interior Repairs	О		•
Grounds Maintenance			
Mowing	A	Bush/shrub trimming	A
Weeding	A	Snow plowing-Streets	A
Mulching	A	Snow plowing-Driveways, Sidewalks	A
Fertilization	A	Snow plowing-Patios	О
Utilities			
Monthly Sewer Expenses	A	Gas Service Meter	О
Monthly Water Expenses	A	Water Service Meter	A
Monthly Electric & Gas Expenses	О	Electric Service Meter	О
Trash Removal	A		
Water,gas,plumbing, electrical lines within exterior walls			

Paint color: 2809 Rockwood Shutter Green- Sherwin Williams All exterior changes require an approved architectural control application